**The Airtex Corporation** 

HVAC Systems - Specialty Metals Commercial / Industrial CSC 1110262

## **REQUEST FOR INFORMATION**

TO:	Anderson-Moore Construction		6/21/2007
	1568 Watertower Road Lake Park, Florida 33403	FAX # CONTRACT NO.	561-840-9813
		CONTRACT NO.	
ATTN:	David O' Donnell	RFI #	3
PROJECT: BUILDING:	American Lung Association		DISCREPANCY CHANGE ORDER DIFF. SITE COND. DELAY INFORMATION REQ.
			SUBSTITUTION
SUBJECT:	Ductwork Chase / Floor penet	ration	
REFERENCE:	Pgs . A1-02-001 - M1-02-101 Column line 6.1 East of "C"		
ISSUE:	Revision # 1 changed the fire dampers from a horizontal wall configuration to a vertical slab mounted installation. This installation shall require Architectural access		
	doors be installed in the walls	on the 2nd floor. The fire dampe	rs will not be accessible
	below the 2nd floor slab due to the installation of turning vanes at the elbows.		
	The duct and drywall access doors must be located within reach of the fire damper. Is it acceptable to have an exposed access door located in the shaft wall ?		
SUGGESTION:			
WE ARE:	[X] Awaiting Directions	The Airtex	Corporation
WE ARE.	[ ] Proceeding		σοιροιαιιοι
Response required by 7/6/2007 or delay will occur. Keith J. Brown   Project Manager			

PH. 561-683-3446 Fax 561-683-3414 1450 B Skees Road - West Palm Beach, Florida 33411 Airtexcorp.com